PATE	0005Z 26 0CT 1962	CI/SSIFIED /	R E T 21 31		UTING	Control of the second
TO :	DIRECTOR		3(b)(1)>25Yr,s			erincens dance grant or engines (any per se engines (any per se engines (any per se
ACTION:	OSA (1-2-3-4-5-6-7 S/C (11) TOR: 0018Z 26 0CT	NO/	Con M		IN 53450	
COL	NELSON ACTING CART NIGHT ACTION	EMFO W	Magan	CIPE	6597	November Committee

- FOR TOTAL TIME OF 17 MINUTES. AB TAKE-OFF WITH WATER, CLIMB TO TEN THOUSAND TO ESTABLISH 400 KEAS CLIMB SCHEDULE. AT THIS POINT PILOT SHALK OBSERVED BOTH ENG OIL PRESSURES READING ZERO, HYDRAULIC PRESSURES READING 400 PSI ALL SYSTEMS, TANK PRESSURES INDICATING MINUS TWO PSI. FLIGHT WAS ABORTED AT THIS TIME AND FUEL DUMPING INITIATED. LANDING MADE WITH SLIGHTLY UNDER TEN THOUSAND POUNDS FUEL REMAINING. DIFFICULTY DETERMINED TO BE BLOWN CIRCUIT BREAKER ON INSTRUMENT.
- 2. PLANNING REFLY SAME FLIGHT EARLY FRIDAY MORNING. ALSO HOPEFUL FLY NUMBER ONE LATER IN DAY.
 - 3. TENTATIVELY PLANNING TWO FLIGHTS ON SATURDAY.

END OF MESSAGE

APPROVED FOR RELEASE DATE: AUG 2007

CECRET

CECNIP 1 Endwied here endematic downqualing and decisalikation